



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

0002

Inspection Report

Minerals Regulatory Program

October 7, 2009

Reviewed: PRB

Mine Name: Black Magic	Permit Number: S/023/0108
Operator Name: Metaminingof Utah	Inspection Date: October 6, 2009
Inspector(s): Wayne Western	Time: 11:15 – 11:50 am
Other Participants: Jerry Mansfield	Mine Status: Pro

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

The purpose of the inspection was to evaluate the site prior to approval and to determine if a reduce bond amount was warranted.

Inspection Summary:

The site can be accessed by existing dirt roads with a four-wheel drive vehicle. The Operator will need to upgrade the road to allow haul trucks and a loader to access the site. Mining will consist of removing the existing stockpiles. Since mining will consist of reclamation (stockpile removal) the Division will allow the Operator to bond for \$8,400 for two acres.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The Division should approve the site to be permitted and that the bond amount be \$8,400 for two acres.

Inspector's Signature

(whw):pb

0002

Inspection Date: October 7, 2009
Page 2 of 4
S/023/0108

cc: (OPERATOR)

Jerry_Mansfield@BLM.gov

O:\M023-Juab\S0230108-BlackMagic\draft\INSP_10062009.doc



Stockpiles



Stockpiles



Top of stockpile



Lady Laird Peak, turn south from Brush road and continue to reach site.